

September 17, 1992

SDMS Document



88402

Ms. Kathy Miller
Case Manager
Industrial Site Evaluation Element
New Jersey Department of Environmental
Protection and Energy
CN 028
401 East State Street, Floor 5
Trenton, New Jersey 08625-0028

RE: August 1992 Monthly Progress
Report on Remedial Activities
at the Former Hexcel Site
205 Main Street, Lodi Borough
Bergen County, New Jersey
ECRA Case No. 86009

Dear Ms. Miller:

On behalf of Hexcel Corporation, Killam Associates (Killam), has prepared this summary report of remedial activities performed at the above referenced site during the period of August 1, 1992 to September 1, 1992. This report satisfies the requirements of Paragraph 36 of the New Jersey Department of Environmental Protection and Energy (NJDEPE) conditional approval letter of July 31, 1990.

A. GROUNDWATER

Collection of Basement Seepage Water

The air stripping towers and incinerator were operated during the month of August, 1992 in order to treat the 3,400 gallons of water collected in the month of July, 1992.

Upper Overburden Aquifer

No additional work was performed relating to the upper overburden aquifer.

Lower Overburden Aquifer

No additional work was performed relating to the lower overburden aquifer.

B. SOILS

Stockpiled Soil

Approximately 140 cubic yards of stockpiled soil currently exists at the Hexcel/Fine Organics facility. Removal and disposal arrangements are being handled by Direct Environmental, Inc. of East Orange, New Jersey. Killam is currently awaiting the waste stream approval from Chemical Waste Management (CWM) in Model City, New York. Disposal of the soil is contingent upon final approval by CWM.

Ms. Miller
September 17, 1992
Page Two

C. GROUNDWATER TREATMENT SYSTEM OPERATION

The 3,400 gallons of basement seepage water collected and treated in the month of July was discharged on August 6, 1992 to the PVSC. The MR-2 forms and the accompanying laboratory analyses of the aforementioned discharge may be found in Appendix A of this report.

The groundwater, LNAPL and DNAPL monitoring plans will be combined into a single report and will be submitted to the NJDEPE on October 15, 1992.

D. DENSE NON-AQUEOUS PHASE LIQUID (DNAPL)

Approximately 500 gallons of water with some DNAPL were recovered during August of 1992. This water was derived from RW7-1 and RW7-5 and was placed in Tank H-7. Approximately 5 gallons of a DNAPL/water mixture were separated out from the 500 gallons of water extracted from the recovery wells.

E. LIGHT NON-AQUEOUS PHASE LIQUID (LNAPL)

The LNAPL recovery system was not operated during the month of August 1992. However, the system will recommence operation upon issuance of the NJPDES SIU Permit.

F. STATUS OF PERMITS

Air Control Apparatus

No activity occurred during this time period.

NJPDES SIU Permit

The Bureau of Industrial Discharge Permits has indicated that the Hexcel NJPDES SIU permit was to be finalized at the end of August, 1992. Hexcel has not yet received this permit.

PVSC Discharge Permit

A final report concerning the feasibility of discharging into the Saddle River was submitted to the PVSC by Environ. A copy of this report will be forwarded to the NJDEPE shortly. Additional information requested by the PVSC was submitted by Environ in a letter dated September 1, 1992. A copy of this letter can be found in Appendix B of this report.

NJPDES Discharge to Groundwater Permit

No activity occurred during this time period.

NJPDES Discharge to Surface Water Permit

No activity occurred during this time period.

Ms. Miller
September 17, 1992
Page Three

G. SCHEDULE UPDATE/NJDEPE MEETING


Killam met with the NJDEPE Case Manager, Technical Coordinator and Case Geologist for Hexcel on August 27, 1992. A follow up letter by the NJDEPE regarding meeting was received by Killam on September 14, 1992. The following is a brief schedule of required materials which the NJDEPE and Killam agreed upon during the August 27th meeting. A more detailed schedule will be submitted in the next progress report.

<u>Item:</u>	<u>Date Due:</u>
Bedrock Aquifer Characterization Study	October 15, 1992
Lower Overburden Aquifer Injection Well Feasibility Report	October 15, 1992
LNAPL/DNAPL/Groundwater Monitoring Program	October 15, 1992
Soil Remedial Needs Study including:	November 15, 1992
<ul style="list-style-type: none">-compilation & review of all soil analyses completed to date;-comparison with Cleanup Standards (issued by the NJDEPE);-preparation of maps showing all results (with MDLs) and exceedences keyed to sample location/depth;-delineation of areas where soil contamination is above Cleanup Standards;-and, preparation of further proposals for addressing contaminated soil areas.	

If you have any questions or comments regarding this report, please do not hesitate to contact me at (201) 912-2489.

Very truly yours,

KILLAM ASSOCIATES


Gary K. Walker
Senior Project Scientist

cc: A. William Nosil, Hexcel Corporation
James Higdon, Fine Organics
Lisa Bromberg, Esq.
Essam Saleh, Hexcel Corporation

DJN:mmma:PROG2

884020003

APPENDIX A

Laboratory Analyses for Basement Seepage Discharge and August 1992 MR-2 Form

US. CHARGE SELF MONITORING PORT

NAME: Fine Organics Corporation

ADDRESS: 205 Main Street, Lodi, NJ 07644

FACILITY LOCATION: _____

OUTLET DESIGNATION (17 DIGITS): 17405041-37430-0171 Outlet # Industrial Sewer

MONITORING PERIOD					
08	01	92	08	31	92
MO	DAY	YEAR	MO	DAY	YEAR
START			END		

Vol Discharged This Period
<u>3,400 GALS</u>
CU.FT X 7.48 = Gallons
Effluent Meter Reading Last Day This Period

DATE	BOD 0310 (mg/l)	TSS 0530 (mg/l)	pH	COD	µg/l PCB	Station Location	Lab Sample #	Gal.
08/05/92	195	29	7.789	950	<0.50	FINAL TANK H1	S-3261	3,400
08/06/92	—	—	—	—	—	DISCHARGE HOSE	S-3267	—
08/06/92 DISCHARGE TO P.V.S.C.								
Influent (Raw) SAMPLING								
07/30/92	NOT ANALYZED				<1.0	TANK H-5, H-7	S-3204	
					ND indicates less than 0.5 µg/l			

SIGNATURE OF PRINCIPAL OR AUTHORIZED AGENT	TYPE NAME AND TITLE	TELEPHONE NO.
<u>Gary K. Walker</u>	GARY K. WALKER	201-912-2489
	Sr. Project Scientist	

PVSC FORM MR-2 REV. 2 1/86

DATE 9/17/92

92JR2043.T1

884020005



**ALL-TEST
ENVIRONMENTAL
LABORATORIES, INC.**

60 Railroad Avenue, Hasbrouck Heights, N.J. 07604
(201) 288-6511 FAX: (201) 288-6887


Method 608 (PCB's)

Project Id. Hexcel
Lab No. S-3204
Client Name: Killam Associates

Matrix: Water
Date Received: 7/22/92
Date Analyzed: 7/28/92

Sample Location	Tank H5	Tank H7	MDL ug/l
PCB-1016	ND	ND	1.0
PCB-1221	ND	ND	1.0
PCB-1232	ND	ND	1.0
PCB-1242	ND	ND	1.0
PCB-1248	ND	ND	1.0
PCB-1254	ND	ND	1.0
PCB-1260	ND	ND	1.0

By:


Irving Berkowitz
Laboratory Manager

MDL = Method Detection Limit
ND = Non Detected



ALL-TEST ENVIRONMENTAL LABORATORIES, INC.

60 Railroad Avenue, Hasbrouck Heights, N.J. 07604


(201) 288-6511 FAX: (201) 288-6887

Volatile Organic Analysis Data

Case Id. Hexcel
Sample No. S-3204 Tank H5
Client Name: Killam Associates

Matrix: Water
Dilution Factor: 1388:1
Date Analyzed: 7/29/92

<u>COMPOUND</u>	<u>UG/L</u>	<u>MDL</u>
Chloromethane	ND	13880
Vinyl Chloride	ND	13880
Bromomethane	ND	13880
Chloroethane	ND	13880
Trichlorofluoromethane	ND	6940
1,1-Dichloroethene	ND	6940
Methylene Chloride	191503.1	6940
Trans-1,2 Dichloroethene	ND	6940
1,1 Dichloroethane	ND	6940
Chloroform	6753J	6940
1,1,1-Trichloroethane	ND	6940
Carbon Tetrachloride	ND	6940
Benzene	ND	6940
1,2-Dichloroethane	ND	6940
Trichloroethene	ND	6940
1,2-Dichloropropane	ND	6940
Bromodichloromethane	ND	6940
Trans-1,3-Dichloropropene	ND	6940
Toluene	7715.5	6940
Cis-1,3-Dichloropropene	ND	6940
1,1,2-Trichloroethane	ND	6940
2-Chloroethyl Vinyl Ether	ND	6940
Tetrachloroethene	58318.3	6940
Dibromochloromethane	ND	6940
Chlorobenzene	17894.8	6940
Ethylbenzene	2004J	6940
m&o Xylenes	ND	13880
p Xylene	ND	13880
Bromoform	ND	6940
1,1,2,2-Tetrachloroethane	ND	6940



**ALL-TEST
ENVIRONMENTAL
LABORATORIES, INC.**

60 Railroad Avenue, Hasbrouck Heights, N.J. 07604
(201) 288-6511 FAX: (201) 288-6887

Volatile Organic Analysis Data

Case Id. Hexcel
Sample No. S-3204 Tank H5
Client Name: Killam Associates


Matrix: Water
Dilution Factor: 1388:1
Date Analyzed: 7/29/92

<u>COMPOUND</u>	<u>UG/L</u>	<u>MDL</u>
1,3-Dichlorobenzene	ND	13880
1,2-Dichlorobenzene	ND	13880
1,4-Dichlorobenzene	ND	13880

ND = None Detected
MDL = Method Detection Limit
J = Below Method Detection Limit
** = Compound Found In Laboratory Blank

<u>SURROGATE COMPOUNDS</u>	<u>RECOVERY</u>	<u>LIMITS</u>
1,2-Dichloroethane-d4	80%	70-121
Toluene-d8	96%	81-117
4-Bromofluorobenzene	100%	74-121

By:


Irving Berkowitz
Laboratory Manager



ALL-TEST ENVIRONMENTAL LABORATORIES, INC.

60 Railroad Avenue, Hasbrouck Heights, N.J. 07604
(201) 288-6511 FAX: (201) 288-6887

Volatile Organic Analysis Data

Case Id. Hexcel
Sample No. S-3204 Tank H7
Client Name: Killam Associates

Matrix: Water
Dilution Factor: 1388:1
Date Analyzed: 7/29/92

<u>COMPOUND</u>	<u>UG/L</u>	<u>MDL</u>
Chloromethane	ND	13880
Vinyl Chloride	ND	13880
Bromomethane	ND	13880
Chloroethane	ND	13880
Trichlorofluoromethane	ND	6940
1,1-Dichloroethene	ND	6940
Methylene Chloride	54126.5	6940
Trans-1,2 Dichloroethene	ND	6940
1,1 Dichloroethane	ND	6940
Chloroform	9315.0	6940
1,1,1-Trichloroethane	21673.8	6940
Carbon Tetrachloride	2118J	6940
Benzene	ND	6940
1,2-Dichloroethane	ND	6940
Trichloroethene	ND	6940
1,2-Dichloropropane	ND	6940
Bromodichloromethane	ND	6940
Trans-1,3-Dichloropropene	ND	6940
Toluene	7902.6	6940
Cis-1,3-Dichloropropene	ND	6940
1,1,2-Trichloroethane	ND	6940
2-Chloroethyl Vinyl Ether	ND	6940
Tetrachloroethene	26703.3	6940
Dibromochloromethane	ND	6940
Chlorobenzene	60831.6	6940
Ethylbenzene	3323J	6940
m&o Xylenes	ND	13880
p Xylene	ND	13880
Bromoform	ND	6940
1,1,2,2-Tetrachloroethane	ND	6940



**ALL-TEST
ENVIRONMENTAL
LABORATORIES, INC.**

60 Railroad Avenue, Hasbrouck Heights, N.J. 07604
(201) 288-6511 FAX: (201) 288-6887

Volatile Organic Analysis Data

Case Id. Hexcel
Sample No. S-3204 Tank H7
Client Name: Killam Associates


Matrix: Water
Dilution Factor: 1388:1
Date Analyzed: 7/29/92

<u>COMPOUND</u>	<u>UG/L</u>	<u>MDL</u>
1,3-Dichlorobenzene	ND	13880
1,2-Dichlorobenzene	ND	13880
1,4-Dichlorobenzene	ND	13880

ND = None Detected
MDL = Method Detection Limit
J = Below Method Detection Limit
** = Compound Found In Laboratory Blank

<u>SURROGATE COMPOUNDS</u>	<u>RECOVERY</u>	<u>LIMITS</u>
1,2-Dichloroethane-d4	79%	70-121
Toluene-d8	89%	81-117
4-Bromofluorobenzene	104%	74-121

By:


Irving Berkowitz
Laboratory Manager

11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100
 101
 102
 103
 104
 105
 106
 107
 108
 109
 110
 111
 112
 113
 114
 115
 116
 117
 118
 119
 120
 121
 122
 123
 124
 125
 126
 127
 128
 129
 130
 131
 132
 133
 134
 135
 136
 137
 138
 139
 140
 141
 142
 143
 144
 145
 146
 147
 148
 149
 150
 151
 152
 153
 154
 155
 156
 157
 158
 159
 160
 161
 162
 163
 164
 165
 166
 167
 168
 169
 170
 171
 172
 173
 174
 175
 176
 177
 178
 179
 180
 181
 182
 183
 184
 185
 186
 187
 188
 189
 190
 191
 192
 193
 194
 195
 196
 197
 198
 199
 200
 201
 202
 203
 204
 205
 206
 207
 208
 209
 210
 211
 212
 213
 214
 215
 216
 217
 218
 219
 220
 221
 222
 223
 224
 225
 226
 227
 228
 229
 230
 231
 232
 233
 234
 235
 236
 237
 238
 239
 240
 241
 242
 243
 244
 245
 246
 247
 248
 249
 250
 251
 252
 253
 254
 255
 256
 257
 258
 259
 260
 261
 262
 263
 264
 265
 266
 267
 268
 269
 270
 271
 272
 273
 274
 275
 276
 277
 278
 279
 280
 281
 282
 283
 284
 285
 286
 287
 288
 289
 290
 291
 292
 293
 294
 295
 296
 297
 298
 299
 300
 301
 302
 303
 304
 305
 306
 307
 308
 309
 310
 311
 312
 313
 314
 315
 316
 317
 318
 319
 320
 321
 322
 323
 324
 325
 326
 327
 328
 329
 330
 331
 332
 333
 334
 335
 336
 337
 338
 339
 340
 341
 342
 343
 344
 345
 346
 347
 348
 349
 350
 351
 352
 353
 354
 355
 356
 357
 358
 359
 360
 361
 362
 363
 364
 365
 366
 367
 368
 369
 370
 371
 372
 373
 374
 375
 376
 377
 378
 379
 380
 381
 382
 383
 384
 385
 386
 387
 388
 389
 390
 391
 392
 393
 394
 395
 396
 397
 398
 399
 400
 401
 402
 403
 404
 405
 406
 407
 408
 409
 410
 411
 412
 413
 414
 415
 416
 417
 418
 419
 420
 421
 422
 423
 424
 425
 426
 427
 428
 429
 430
 431
 432
 433
 434
 435
 436
 437
 438
 439
 440
 441
 442
 443
 444
 445
 446
 447
 448
 449
 450
 451
 452
 453
 454
 455
 456
 457
 458
 459
 460
 461
 462
 463
 464
 465
 466
 467
 468
 469
 470
 471
 472
 473
 474
 475
 476
 477
 478
 479
 480
 481
 482
 483
 484
 485
 486
 487
 488
 489
 490
 491
 492
 493
 494
 495
 496
 497
 498
 499
 500
 501
 502
 503
 504
 505
 506
 507
 508
 509
 510
 511
 512
 513
 514
 515
 516
 517
 518
 519
 520
 521
 522
 523
 524
 525
 526
 527
 528
 529
 530
 531
 532
 533

Table 1. *Continued*